

#### MM TEST TRIAL

Concrete flooring under greenhouse table cleaned and left untreated for 6 months. Significant regrowth occurring.

#### MM TEST TRIAL

Greenhouse concrete pathway cleaned and not treated. Significant regrowth occurring.

#### MM TEST TRIAL

Concrete flooring under greenhouse table cleaned and treated with Mold Manager. No regrowth after 6 months.

#### MM TEST TRIAL

Greenhouse concrete pathway cleaned and treated with Mold Manager. No regrowth after 6 months.

Courtesy Iwasaki Brothers Greenhouse



### MM TEST TRIAL

Concrete flooring under greenhouse tables cleaned and left untreated. Significant regrowth occurring.

### MM TEST TRIAL

Greenhouse under-table treated with Mold Manager. No regrowth after 7 months.

Courtesy Iwasaki Brothers Greenhouse



### MM TEST TRIAL

Concrete flooring under greenhouse tables cleaned and left untreated. Significant regrowth occurring.

#### MM TEST TRIAL

Greenhouse under-table treated with Mold Manager. No regrowth after 7 months.

Courtesy Iwasaki Brothers Greenhouse





MM TEST TRIAL

Greenhouse #2 cleaned and left untreated August, 2012. 2 years later, significant regrowth has occurred.

#### MM TEST TRIAL

Greenhouse #1 cleaned and treated with Mold Manager August, 2012. 2 years later, no regrowth.



#### MM SIDE-BY-SIDE TEST TRIAL

Both sides cleaned - Left side untreated, Right side treated with Mold Manager. Significant regrowth on untreated side after 6 months.

#### MM SIDE-BY-SIDE TEST TRIAL

Both sides cleaned - Left side untreated, Right side treated with Mold Manager. Significant regrowth on untreated side after 6 months.



#### MM SIDE-BY-SIDE TEST TRIAL

Entire panel cleaned - Bottom untreated, Top of panel treated with Mold Manager. Significant regrowth on untreated section after 6 months.

#### MM SIDE-BY-SIDE TEST TRIAL

Both sides cleaned - Right side untreated, Left side treated with Mold Manager. Significant regrowth on untreated side after 6 months.